

AD-A087 536


NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON  
NATIONAL DAM SAFETY PROGRAM, STAR LAKE UPPER DAM (NJ00221), DEL--ETC(U)  
FEB 80 W GUINAN

F/G 13/13  
DACPW61-79-C-0011  
NL


UNCLASSIFIED

1 of 2

AD-A087 536



LEVEL IV



ADA 087536

DELAWARE RIVER BASIN  
TRIBUTARY TO PEQUANNOCK RIVER  
PASSAIC COUNTY  
NEW JERSEY

**STAR LAKE UPPER DAM  
NJ 00221**

PHASE 1 INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

DTIC ELECTE  
S D  
AUG 6 1980  
D



APPROVED FOR PUBLIC RELEASE;  
DISTRIBUTION UNLIMITED.

DEPARTMENT OF THE ARMY

Philadelphia District  
Corps of Engineers  
Philadelphia, Pennsylvania

80 8 4 092  
FEBRUARY 1980

APPROVED FOR PUBLIC RELEASE;  
DISTRIBUTION UNLIMITED.

FILE COPY

**UNCLASSIFIED**

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NJ00221	2. GOVT ACCESSION NO. <i>AD-A087 536</i>	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Star Lake Upper Dam Passaic County, New Jersey	5. TYPE OF REPORT & PERIOD COVERED FINAL	
7. AUTHOR(s) WARREN GUINAN	6. PERFORMING ORG. REPORT NUMBER DACW61-79-C-0011 ✓	
9. PERFORMING ORGANIZATION NAME AND ADDRESS Anderson-Nichols 6 London Rd. Concord, N.H. 03301	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
11. CONTROLLING OFFICE NAME AND ADDRESS NJ Department of Environmental Protection ✓ Division of Water Resources P.O. Box CN029 Trenton, NJ 08625	12. REPORT DATE Feb. 1980	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, PA 19106	13. NUMBER OF PAGES 104	
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.	15. SECURITY CLASS. (of this report) Unclassified	
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia 22151.	Accession No. NIIS GRANT DDC TAB Unannounced Justification _____  By _____  Distribution/ Availability Codes Dist. Avail and/or special <i>A</i>	
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams Eembankments Visual Inspection Structural Analysis	National Dam Safety Program, Star Lake Upper Dam, New Jersey Erosion	
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's adequacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.		

*410871*

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

**NOTICE**

THIS DOCUMENT HAS BEEN REPRODUCED  
FROM THE BEST COPY FURNISHED BY  
THE SPONSORING AGENCY. ALTHOUGH  
IT IS RECOGNIZED THAT CERTAIN POR-  
TIONS ARE ILLEGIBLE, IT IS BEING  
RELEASED IN THE INTEREST OF MAKING  
AVAILABLE AS MUCH INFORMATION AS  
POSSIBLE.



DEPARTMENT OF THE ARMY  
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
CUSTOM HOUSE-2 D & CHESTNUT STREETS  
PHILADELPHIA, PENNSYLVANIA 19106

IN REPLY REFER TO  
NAPEN-N

DTIC  
SELECTED  
AUG 6 1980

D

28 JUL 1980

Honorable Brendan T. Byrne  
Governor of New Jersey  
Trenton, New Jersey 08621

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Star Lake Upper Dam in Passaic County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Star Lake Upper Dam, a high hazard potential structure, is judged to be in good overall condition. The dam's spillway is considered inadequate because a flow equivalent to 15 percent of the Spillway Design Flood - SDF - would cause the dam to be overtopped. (The SDF, in this instance, is one half of the Probable Maximum Flood.) The decision to consider the spillway "inadequate" instead of "seriously inadequate" is based on the determination that dam failure resulting from overtopping would not significantly increase the hazard of loss of life downstream from the dam from that which would exist just before overtopping failure. To ensure adequacy of the structure, the following actions, as a minimum are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Within three months of the consultant's findings, remedial measures to ensure spillway adequacy should be initiated. In the interim, a detailed emergency operation plan and warning system should be promptly developed. Also during periods of unusually heavy precipitation, around the clock surveillance should be provided.

b. Within twelve months from the date of approval of this report, engineering studies and analyses should be performed to:

(1) Design and oversee procedures for the removal of trees from the upstream slope of the dam.

NAPEN-N

Honorable Brendan T. Byrne

(2) Design and oversee the installation of erosion protection for the upstream slope of the dam.

(3) Evaluate the potential for erosion and undermining of the downstream toe of the dam if water is discharged from the outlet pipe near the left abutment.

(4) Investigate the cause of the leakage that is discharging from the dry stone-masonry wall on the downstream side of the dam near the right abutment, and design remedial measures if needed.

Initiate any recommended remedial action within three months of study completion.

c. Within one year from the date of approval of this report, the owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.

d. Within six months from the date of approval of this report, the following remedial actions should be initiated:

(1) Establish grassy vegetation on the embankment.

(2) Clean and paint the rusted steel member embedded in the spillway crest and rusted portions of the service bridge.

(3) Repair spalled and eroded concrete surfaces of the spillway abutments and stone-masonry wall caps.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Roe of the Eighth District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

NAPEN-N

Honorable Brendan T. Byrne

An important aspect of the Dam Inspection Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,



1 Incl  
As stated

JAMES G. TON  
Colonel, Corps of Engineers  
District Engineer

Copies furnished:

Mr. Dirk C. Hofman, P.E., Deputy Director  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CN029  
Trenton, NJ 08625

Mr. John O'Dowd, Acting Chief  
Bureau of Flood Plain Regulation  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CN029  
Trenton, NJ 08625

**STAR LAKE UPPER DAM (NJ0221)**

**CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS**

This dam was inspected on 8 November 1979, by Anderson-Nichols & Co., Inc. under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Star Lake Upper Dam, a high hazard potential structure, is judged to be in good overall condition. The dam's spillway is considered inadequate because a flow equivalent to 15 percent of the Spillway Design Flood - SDF - would cause the dam to be overtopped. (The SDF, in this instance, is one half of the Probable Maximum Flood.) The decision to consider the spillway "inadequate" instead of "seriously inadequate" is based on the determination that dam failure resulting from overtopping would not significantly increase the hazard of loss of life downstream from the dam from that which would exist just before overtopping failure. To ensure adequacy of the structure, the following actions, as a minimum are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Within three months of the consultant's findings, remedial measures to ensure spillway adequacy should be initiated. In the interim, a detailed emergency operation plan and warning system should be promptly developed. Also during periods of unusually heavy precipitation, around the clock surveillance should be provided.

b. Within twelve months from the date of approval of this report, engineering studies and analyses should be performed to:

(1) Design and oversee procedures for the removal of trees from the upstream slope of the dam.

(2) Design and oversee the installation of erosion protection for the upstream slope of the dam.

(3) Evaluate the potential for erosion and undermining of the downstream toe of the dam if water is discharged from the outlet pipe near the left abutment.

(4) Investigate the cause of the leakage that is discharging from the dry stone-masonry wall on the downstream side of the dam near the right abutment, and design remedial measures if needed.


Initiate any recommended remedial action within three months of study completion.

c. Within one year from the date of approval of this report the owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.

d. Within six months from the date of approval of this report, the following remedial actions should be initiated:

- (1) Establish grassy vegetation on the embankment.
- (2) Clean and paint the rusted steel member embedded in the spillway crest and rusted portions of the service bridge.
- (3) Repair spalled and eroded concrete surfaces of the spillway abutments and stone-masonry wall caps.

APPROVED:



JAMES G. TON

Colonel, Corps of Engineers  
District Engineer

DATE:



9) File No. 10  
15) DACW61-79-C-0012 (Master)  
10) Guinan 11) Oct 87

6) PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Star Lake Upper Dam  
Identification No.: Fed ID No. (NJ00221), 1 man  
State Located: New Jersey  
County Located: Passaic  
Stream: Tributary to Pequannock River  
River Basin: Passaic River, New Jersey  
Date of Inspection: November 8, 1979

ASSESSMENT OF GENERAL CONDITIONS

Star Lake Upper Dam is about 80 years old and in good overall condition. It is small in size and is classified as High Hazard. The crest of the dam consists of concrete cap walls on upstream and downstream faces with a bare dirt path in between. Trees up to 5 inches in diameter are growing on the crest and upstream face of the dam. The riprap on the upstream face is in poor condition. There is some rusting and erosion of the embedded steel member in the spillway crest and steel of the service bridge. There is also some spalling of the spillway abutments. Some leakage is discharging from the dry stone-masonry on the downstream side of the dam near the right abutment. The spillway can pass approximately 14 percent of the PMF and is inadequate.

It is recommended that the owner retain the services of a professional engineer, qualified in the design and construction of dams, to accomplish the following in the future: design and oversee procedures for the removal of trees and their root system from the upstream slope of the dam; design and oversee the installation of erosion protection for the upstream slope of the dam; evaluate the potential for erosion and undermining of the downstream toe of the dam if water is discharged from the outlet pipe near the left abutment; investigate the cause of the leakage that is discharging from the dry stone-masonry wall on the downstream side of the dam near the right abutment, and design remedial measures if needed; and conduct a more detailed hydrologic and hydraulic analysis of the watershed, reservoir, dam and spillway to determine the extent and type of remedial measures necessary.

It is further recommended that the owner accomplish the following tasks as a part of operating and maintenance procedures: in the near future, establish a surveillance program for use during and immediately after periods of heavy rainfalls, and also a warning system to follow in case of emergency conditions; establish grassy vegetation on the embankment; clean and paint the rusted steel imbedded members; and repair spalled and eroded concrete surfaces of the spillway abutments and stone masonry wall caps. Within one year from the date of approval of this report, the owner should develop written operating procedures and a periodic maintenance plan to insure the safety of the dam.

ANDERSON-NICHOLS & COMPANY, INC.

Warren A. Guinan  
Warren A. Guinan, P.E.  
Project Manager  
New Jersey No. 16848

410871

November 3, 1979

OVERVIEW  
Star Lake Upper Dam



## CONTENTS

### PHASE I INSPECTION REPORT NATIONAL DAM SAFETY REPORT

STAR LAKE UPPER DAM FED ID NO. NJ00221 N.J. 22-52

		<u>Page</u>
SECTION 1	PROJECT INFORMATION	
1.1	<u>General</u>	1
1.2	<u>Project Description</u>	1
1.3	<u>Pertinent Data</u>	2
SECTION 2	ENGINEERING DATA	
2.1	<u>Design</u>	5
2.2	<u>Construction</u>	5
2.3	<u>Operation</u>	5
2.4	<u>Evaluation</u>	5
SECTION 3	VISUAL INSPECTION	6
SECTION 4	OPERATIONAL PROCEDURES	
4.1	Procedures	7
4.2	Maintenance of Dam	7
4.3	Maintenance of Operating Facilities	7
4.4	Warning System	7
4.5	Evaluation of Operational Adequacy	7
SECTION 5	HYDRAULIC/HYDROLOGIC	8
SECTION 6	STRUCTURAL STABILITY	9
SECTION 7	ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES	
7.1	<u>Assessment</u>	10
7.2	<u>Recommendations/Remedial Measures</u>	10
FIGURES	1. Essential Project Features	
	2. Regional Vicinity Map	
APPENDICES	1. Check List Visual Inspection	
	2. Photographs	
	3. Hydrologic Computations	
	4. References	

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY INSPECTION PROGRAM  
STAR LAKE UPPER DAM  
FED ID No. #NJ00221 NJ No. #22-52

SECTION 1  
PROJECT INFORMATION

1.1 General

a. Authority. Authority to perform the Phase I Safety Inspection of Star Lake Upper Dam was received from the State of New Jersey, Department of Environmental Protection, Division of Water Resources by letter dated 26 October 1979 under Contract No. FPM-39 dated 28 June 1978. This Authority was given pursuant to the National Dam Inspection Act, Public Law 92-367 and by agreement between the State and the U.S. Army Engineers District, Philadelphia. The inspection discussed herein was performed by Anderson-Nichols & Company, Inc. on 5 November 1979.

b. Purpose. The purpose of the Phase I Investigation is to develop an assessment of the general conditions with respect to the safety of Star Lake Upper Dam and appurtenances based upon available data and visual inspection, and determine any need for emergency measures and conclude if additional studies, investigations, and analyses are necessary and warranted.

1.2 Project Description

a. Description of Dam and Appurtenances. Star Lake Upper Dam is a 200-foot long earthfill and stone masonry dam with a hydraulic height of 10 feet and structural height of 10.5 feet. The downstream face is of stone masonry with a vertical slope and the upstream face is of earth and rock with a 1H:1V slope. The 52-foot long concrete free overflow spillway is near the center of the dam. A bridge extends along the crest of the dam. There are 25-foot long and 11-foot long 18-inch diameter concrete pipe low-level outlets located on west (right) and east (left) abutments respectively, about 2 feet above the toe of the embankment. Operating mechanisms for the low-level outlets are located on the upstream slope of the embankment a few feet upstream of the normal water line. Essential features of the dam are given in Figure 1.

b. Location. The dam is located in Passaic County, New Jersey on a tributary to the Pequannock River, approximately 1.5 miles north of Bloomingdale. It is a north latitude  $41^{\circ} 1'4''$  and west longitude  $74^{\circ}21.0'$ . A location map is given in Figure 2.

c. Size Classification. Star Lake Upper Dam is classified as being small in size on the basis of storage at the dam crest of 150 acre-feet, which is less than 1000 acre-feet but more than 50 acre-feet, and on the basis of its height of 10 feet, which is less than

40 feet, in accordance with criteria given in the Recommended Guidelines for Safety Inspection of Dams.

d. Hazard Classification. Visual inspection of the downstream area and the breach analysis contained herein show that failure of Star Lake Upper Dam would lead to the overtopping of Star Lake Lower Dam downstream, which could lead to severe damage to three structures just downstream of Star Lake Lower Dam and possible loss of more than a few lives (downstream area is a camp and the structures are used part of the year). Star Lake Upper Dam is thus classified as High Hazard.

e. Ownership. The dam is owned by the Salvation Army. Captain Israel Gaither, 546 Avenue of the Americas, New York, New York, 10011, (212) 255-9400 is the responsible party.

f. Purpose of Dam. The lake is used for recreation.

g. Design and Construction History. No information was found regarding the original design and construction of the dam which took place around 1900.

h. Normal Operational Procedures. The lake level is lowered every fall to protect the docks from ice.

i. Site Geology. No site specific geologic information (such as borings) was available at the time the dam was inspected. Information derived from a report entitled "Engineering Geology of the Northeast Corridor, Washington, D.C. to Boston, MA" and the Geologic Map of New Jersey (Lewis and Kummel, 1912) indicate that soils within the immediate site area consist of ground moraine overlying bedrock. Bedrock was observed in extensive outcrops located at the right abutment and adjacent hillside during inspection of this dam. The previously mentioned report indicates that bedrock in this area consists of granitoid gneiss with occasional migmatite, granulite, amphibolite and granitic rocks of Precambrian age.

### 1.3 Pertinent Data

a. Drainage Area

1.10 square miles

b. Discharge at Damsite (cfs)

Maximum flood at damsite - unknown

Low-level outlets at spillway crest elevation (if operable)-  
35.7

Total ungated spillway capacity at maximum pool elevation -  
334

c. Elevation (NGVD)

Top of dam - 531.6

Design surcharge ( $\frac{1}{2}$  PMF) - 533

Recreation pool (at time of inspection) - 530

Spillway crest - 529.9

Streambed at centerline of dam - 521.6

Maximum tailwater (estimated) - 527.1

d. Reservoir (feet)

Length of maximum pool - 1900

Length of recreation pool - 1500

e. Storage (acre-feet)

Recreation pool - 115

Design surcharge ( $\frac{1}{2}$  PMF) - 183

Top of dam - 150

f. Reservoir Surface (acres)

Top of dam - 21.5

Spillway crest - 16.5

g. Dam

Type - earthfill stone masonry

Length - 200 feet

Height - 10 feet (hydraulic)

- 10.5 feet (structural)

Top width - 5 to 10 feet

Side slopes - upstream 1H:1V, downstream vertical

Zoning - unknown

Impervious core - unknown

Cutoff - unknown

Grout curtain - unknown

h. Spillway

Type - free overflow

Length of weir - 52'

Crest elevation - 529.9' NGVD

Gates - none

U/S Channel - Star Lake Upper

D/S Channel - Star Lake Lower

i. Regulating Outlets

Type - two 18-inch diameter concrete low-level outlet pipes

Length (estimated) - 12 and 25 feet

Access - on upstream slope of embankment a few feet from  
shore at normal pool

SECTION 2  
ENGINEERING DATA

2.1 Design

No plans, hydraulic or hydrologic data for Star Lake Upper Dam were found.

2.2 Construction

No recorded data concerning construction of Star Lake Upper Dam were disclosed. Reference data on file with the New Jersey Department of Environmental Protection indicates that the dam was built in 1900 by Star Safety Razor Company. The date on the left, low-level gate operating structure indicates that it was added to the dam in 1970.

2.3 Operation

No engineering operational data were found.

2.4 Evaluation

a. Availability. A search of the New Jersey Department of Environmental Protection files, and contact with the owner revealed only a limited amount of recorded information.

b. Adequacy. Because of the limited amount of recorded data available, evaluation of this dam was based solely on visual observations.

SECTION 3  
VISUAL INSPECTION

3.1 Findings

a. Dam. Trees are growing on the upstream slope of the dam. There appear to be remnants of riprap on the upstream slope, but it is in poor condition and there is very little riprap above the waterline. Some leakage is discharging from the dry stone-masonry wall on the downstream side of the dam near the right abutment. There is no vegetation on the crest of the dam between the concrete cap walls on the upstream and downstream edges of the crest. There is no vegetation on the embankment next to the left abutment.

b. Appurtenant Structures. Discharge from the low-level outlet pipe near the left abutment is channeled along the downstream toe of the dam at the base of the dry stone-masonry wall which constitutes the downstream side of the dam. It is not possible to determine on the basis of the visual inspection whether there is any potential for erosion and undermining of the wall when water is flowing in this channel.

There is some rusting and erosion of the imbedded steel member in the spillway crest, and some spalling of the spillway abutment. Portions of the service bridge exhibit minor rust.

SECTION 4  
OPERATIONAL PROCEDURES

4.1 Procedures

No formal operating procedures were found. The low-level outlet gates are opened every fall.

4.2 Maintenance of Dam

No formal maintenance procedures for the dam were found

4.3 Maintenance of Operating Facilities

No formal maintenance procedures for operating facilities were found.

4.4 Warning System

No description of any warning system was found.

4.5 Evaluation of Operational Adequacy

Because of the lack of operation and maintenance procedures, the remedial measures described in Section 7.2 should be implemented as prescribed.

SECTION 5  
HYDROLOGIC/HYDRAULIC

5.1 Evaluation of Features

a. Design Data. Since no data were disclosed an evaluation could not be performed.

b. Experience Data. No experience data were found.

c. Visual Observations. No visual evidence was found of damage to the structure caused by overtopping. At the time of inspection approximately 0.1 foot of water was passing over the free overflow spillway.

d. Overtopping Potential. The hydraulic/hydrologic evaluation for Star Lake Upper Dam is based on a Spillway Design Flood (SDF) equal to one-half the Probable Maximum Flood (PMF) in accordance with the range of test floods given in the evaluation guidelines for dams classified as high hazard and small in size. The effects of Lake Kampfe, immediately upstream, were considered in the analysis. The PMF has been determined by application of the SCS Dimensionless Unit Hydrograph procedure to a 24-hour probable maximum storm of 22 inches. Hydrologic computations are given in Appendix 3. The routed half-PMF peak discharge for the subject watershed is approximately 2200 cfs. The minimum elevation of the dam allows 1.7 feet of depth in the spillway before overtopping occurs. Under this head the spillway capacity is 334 cfs, which is less than the selected SDF.

Flood routing calculations indicate that Star Lake Upper Dam will be overtopped for more than 6 hours to a maximum depth of 1.48 feet under half-PMF conditions. It is estimated that the spillway can pass about 14 percent of the PMF without overtopping the dam, thus the spillway is considered inadequate.

Because the dam was classified as High Hazard based on visual observation, a breach analysis was performed to assess the increase in downstream hazard dam failure conditions. The results of the breach analysis, contained in Appendix 3, show that the downstream hazard is clearly high but is not increased under dam failure conditions.

e. Drawdown Capability. Assuming that the low-level outlet currently in place is in operable condition, it is estimated that the lake can be drained in approximately 1.5 days assuming no significant inflow. This time period is considered adequate for draining the reservoir in an emergency situation.

SECTION 6  
STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations. Trees growing on the crest of the dam may cause seepage and erosion problems if they blow over and pull out their roots or if they die or are cut and their roots rot. The poor condition of the riprap on the upstream slope makes the slope susceptible to erosion. Leakage discharging from the dry stone-masonry wall on the downstream side of the dam near the right abutment may lead to a long-term stability problem. The lack of vegetation on the crest of the dam, at the right end of the dam, and on the entire embankment at the left abutment of the dam makes those areas susceptible to erosion if the dam should be overtopped. There is a possibility that if water discharges from the low-level outlet pipe at the left end of the dam, it may cause erosion or undermining of the dry stone-masonry wall on the downstream side of the dam. Based on the visual inspection alone, it is not possible to determine the character of the dam foundation or the interior of the cross section. Therefore, it is not possible to evaluate the factor of safety of the dam against slope failure, sliding, or overturning.

b. Design and Construction Data. No design or construction data pertinent to the structural stability of the dam are available.

c. Operating Records. No operating records pertinent to the structural stability of the dam are available.

d. Post-Construction Changes. No record of post-construction changes pertinent to the stability of the dam is available. The date on the left low-level outlet indicates it was added in 1970.

e. Seismic Stability. This dam is in Seismic Zone 1. According to the Recommended Guidelines, dams located in Seismic Zone 1 "may be assumed to present no hazard from earthquake provided static stability conditions are satisfactory and conventional safety margins exist". None of the visual observations made during the inspection are indicative of unstable slopes. However, because no data are available concerning the engineering properties of the embankment and foundation materials for this dam, it is not possible to make an engineering evaluation of the stability of the slopes or the factor of safety under static conditions.

SECTION 7  
ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition. Star Lake Upper Dam is 80 years old and is in good condition.

b. Adequacy of Information. The information available is such that the assessment of this dam must be based primarily on the results of the visual inspection.

c. Urgency. The recommendations made in Sections 7.2 should be implemented by the owner as prescribed below.

d. Necessity for Additional Data/Evaluation. The information available from the visual inspection is adequate to identify the potential problems which are listed in 7.2 a. below. These problems require the attention of a professional engineer qualified in the design and construction of dams who will have to make additional engineering studies to design or specify remedial measures to rectify the problems. The two lakes located upstream and downstream of Star Lake Upper Dam must be considered in this analysis. If left unattended, the problems could lead to failure of the dam.

7.2 Recommendations/Remedial Measures

a. Recommendations. The owner should retain a professional engineer qualified in the design and construction of dams to do the following things in the future:

(1) Design and oversee procedures for the removal of trees and their root systems from the upstream slope of the dam.

(2) Design and oversee the installation of erosion protection for the upstream slope of the dam.

(3) Evaluate the potential for erosion and undermining of the downstream toe of the dam if water is discharged from the outlet pipe near the left abutment.


(4) Investigate the cause of the leakage that is discharging from the dry stone-masonry wall on the downstream side of the dam near the right abutment, and design remedial measures if needed.

(5) Conduct a more detailed hydrologic and hydraulic analysis of the watershed, reservoir, dam, and spillway to determine the extent and type of remedial measures necessary.

The owner should accomplish the following in the near future:


- 1) Establish a surveillance program for use during and immediately after periods of heavy rainfall, and also a warning system to follow in case of emergency conditions.
- 2) Establish grassy vegetation on the embankment.
- 3) Clean and paint the rusted steel member embedded in the spillway crest and rusted portions of the service bridge.
- 4) Repair spalled and eroded concrete surfaces of the spillway abutments and stone-masonry wall caps.

Within one year from the date of approval of this report, the owner should develop written operating procedures and a periodic maintenance plan to insure the safety of the dam.




STAR LAKE

### ELEVATION A-A



### SECTION B-B

PL



PLAN

DRAWN FROM FIELD INSPECTION DATA 11/8/79

Anderson-Nichols & Co., Inc.

CONCORD

U.S. ARMY ENGINEER DIST. PHILADELPHIA

CORPS OF ENGINEERS

PHILADELPHIA, PA.

NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS

## STAR LAKE UPPER DAM

TRIBUTARY TO PEQUANNOCK BROOK

NEW JERSEY

SCALE: NOT TO SCALE

DATE: JANUARY 1980



SCALE IN MILES

0 5 10

MAP BASED ON STATE OF NEW JERSEY  
OFFICIAL HIGHWAY MAP AND GUIDE.

Anderson-Nichols & Co., Inc.

CONCORD

NEW HAMPSHIRE

U.S. ARMY ENGINEER DIST. PHILADELPHIA  
CORPS OF ENGINEERS  
PHILADELPHIA, PA.

### NATIONAL PROGRAM OF INSPECTION OF NON-FED.DAMS

## STAR LAKE UPPER DAM LOCATION MAP

TRIBUTARY TO PEQUANNOCK RIVER

NEW JERSEY

SCALE: SEE BAR SCALE

DATE: JANUARY 1980

FIGURE - 2

APPENDIX 1  
VISUAL INSPECTION  
CHECKLIST

STAR LAKE UPPER DAM

Check List  
Visual Inspection  
Phase 1

Name	Dam	Star Lake	Upper Dam	County	Passaic	State	NJ	Coordinators	NJDEP
Date(s)	Inspection	Nov. 8, 1979	Weather	cloudy, cool		Temperature	60° F		
Pool Elevation at Time of Inspection	530'	NGVD	Tailwater at Time of Inspection	524.2'	NGVD				NGVD

Inspection Personnel:

Warren Guinan	Ronald Hirschfeld
Stephen Gilman	
Janusz Czyzowski	

Gilman/Hirschfeld Recorder

## EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	Concrete capped stone-masonry, several cracks in concrete cap. No significant indication of movement.	Repair and seal cracks.
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Bare ground and erosion of both upstream and downstream sides of embankment at left abutment.	Repair erosion and provide adequate erosion protection.
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Good.	
RIPRAP FAILURES	Remnants of riprap below water level on upstream slope appear to be in poor condition. Limited amount of riprap above water level. Small trees growing on upstream edge of crest.	Remove trees and provide adequate erosion protection on upstream slope.

## EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
RAILINGS		
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Good. (See also "Sloughing or Erosion..." above.)	Investigate and implement remedial measures if necessary.
ANY NOTICEABLE SEEPAGE	One minor seepage from downstream dry masonry wall near right abutment.	
STAFF GAGE AND RECORDER	None observed.	
DRAINS	None observed.	

UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Good condition-surface erosion of surface laitance of concrete. Steel channel weir embeded in concrete is rusted and corroded. Right training wall at spillway abutment is spalled and eroded.	Clean and paint rusted steel. Repair spalled concrete.
APPROACH CHANNEL	Wide and unobstructed.	
DISCHARGE CHANNEL	Discharge passes directly into small pond which is impounded by another dam immediately downstream.	
BRIDGE AND PIERS OVER SPILLWAY	Good condition. Some surface rust on steel columns and beams. Minor weathering of deck.	Clean and paint areas showing rust.

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT		
INTAKE STRUCTURE	Not visible.	
OUTLET PIPE	Left end - major crack on top of pipe.	Monitor - if crack worsens it should be repaired.
OUTLET CHANNEL	Discharge passes directly into small pond which is impounded by another dam immediately downstream.	
EMERGENCY GATE		Left gate - not visible, no leakage observed in outlet pipe. Operating mechanism is in good condition. Right gate - not visible, gate operating mechanism is in good condition.

VISUAL EXAMINATION OF RESERVOIR	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Moderately to steeply sloping and wooded.	
SEDIMENTATION	No evidence of significant sedimentation observed.	

DOWNTSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Wide, an unobstructed spillway drains directly into Star Lake Lower.	
SLOPES	General area in vicinity of lower pond is flat.	
APPROXIMATE NO. OF HOMES AND POPULATION.	Three camp buildings - population varies with season.	

CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
PLAN OF DAM	None found
REGIONAL VICINITY MAP	Prepared for this report.
CONSTRUCTION HISTORY	None found
TYPICAL SECTIONS OF DAM	None.
HYDROLOGIC/HYDRAULIC DATA	None.
OUTLETS - PLAN	None.
- DETAILS	None found
- CONSTRAINTS	None found
- DISCHARGE RATINGS	None found
RAINFALL/RESERVOIR RECORDS	None found

ITEM	REMARKS
DESIGN REPORTS	None found
GEOLOGY REPORTS	None found
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	None found
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	None found
POST-CONSTRUCTION SURVEYS OF DAM	None found
BORROW SOURCES	Unknown.

<u>ITEM</u>	<u>REMARKS</u>
MONITORING SERVICES	None.
MODIFICATIONS	None.
HIGH POOL RECORDS	None.
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None.
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	None.
MAINTENANCE OPERATION RECORDS	None.

<u>ITEM</u>	<u>REMARKS</u>
SPILLWAY PLAN	Prepared for this report from field inspection.
SECTIONS	
DETAILS	None.
OPERATING EQUIPMENT	Two gate valves.
PLANS & DETAILS	None.

CHECK LIST  
HYDROLOGIC AND HYDRAULIC DATA  
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: Mountainous, heavy forest

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 530' NGVD (115)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): Not applicable

ELEVATION MAXIMUM DESIGN POOL: 533' NGVD

ELEVATION TOP DAM: 531.6' NGVD

CREST: Free overflow concrete capped spillway.

- a. Elevation 529.9' NGVD
- b. Type concrete weir
- c. Width 6 feet
- d. Length 52 feet
- e. Location Spillover center of the dam
- f. Number and Type of Gates

OUTLET WORKS: Two low-level outlet pipes

- a. Type 18-inch diameter concrete pipes
- b. Location on right and left abutments
- c. Entrance Inverts Unknown
- d. Exit Inverts 826.5' NGVD
- e. Emergency Draindown Facilities (described above)

HYDROMETEORLOGICAL GAGES: None

- a. Type
- b. Location
- c. Records

MAXIMUM NON-DAMAGING DISCHARGE: 334 cfs

**APPENDIX 2**

**PHOTOGRAPHS**

**STAR LAKE UPPER DAM**



November 8, 1979

View of the crest of the dam from left abutment  
looking west.



November 8, 1979

View of the crest of the dam from right abutment  
looking east.




November 8, 1979

View of the upstream face of the free overflow  
spillway.



November 8, 1979


View of the upstream reservoir from the dam crest.



November 8, 1979  
Upstream face of the dam from left embankment.



November 8, 1979  
View of the low-level outlet gate on the left  
of the spillway from left embankment.




November 8, 1979

View of the low-level outlet gate on the right  
of the spillway from dam crest.



November 8, 1979

Low-level outlet of the left abutment.



November 8, 1979  
Seepage at the downstream face of right abutment.



November 8, 1979  
View of the junction of the right training wall  
and the spillway showing spalling of the concrete  
on the surface.



November 8, 1979  
View of the downstream channel from the dam crest.

APPENDIX 3  
HYDROLOGIC COMPUTATIONS

STAR LAKE UPPER DAM

Anderson-Nichols & Company, Inc.

Subject STAR LAKE UPPER DAM

Sheet No. 1 of \_\_\_\_\_  
Date 11-28-79  
Computed 8/24/78  
Checked FOD

JOB NO. 3409-09

SQUARES  
1/4 IN SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

1

2

3

## HYDROLOGIC COMPUTATIONS

4

NAME : STAR LAKE UPPER DAM

5

LOCATION : PASSAIC COUNTY, N.J.

6

DRAINAGE AREA : 1.10 Mi<sup>2</sup>

7

SURFACE AREA (NORMAL POOL) : 16.5 ac

8

EVALUATION CRITERIA:

9

SIZE : SMALL

10

HAZARD : HIGH

11

SPILLWAY DESIGN FLOOD: BASED ON SIZE AND  
CLASSIFICATION, THE SPILLWAY DESIGN FLOOD  
WILL BE THE  $\frac{1}{2}$  PMF ( $\frac{1}{2}$  THE PROBABLE MAXIMUM  
FLOOD) WITH A PEAK INFLOW OF 2438 CFS.

12

13

NOTE: DRAINAGE AREA AND SURFACE AREA  
OF STAR LAKE UPPER DAM WERE PLANIMETERED.

14

15

16

17

18

19

20

21

22

23

JOB NO. 3409 - 09

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
1/4 IN. SCALE

1

2

BESIDES STAR LAKE UPPER THERE IS KAMPFF LAKE LOCATED UPSTREAM, WITHIN STAR LAKE UPPER DAM DRAINAGE AREA, WHICH OCCUPIES 0.86 MI<sup>2</sup> OF THE TOTAL 1.10 MI<sup>2</sup> DRAINAGE AREA. USING THE HEC-1 PROGRAM AN INFLOW HYDROGRAPH WAS DETERMINED AND ROUTED THROUGH THE KAMPFF LAKE TO DETERMINE THE OUTFLOW FROM KAMPFF LAKE DAM. THIS OUTFLOW COMBINED WITH INFLOW HYDROGRAPH OF STARLAKE UPPER DAM DRAINAGE AREA (0.24 MI<sup>2</sup>) COMPROMISES THE TOTAL INFLOW INTO THE STAR LAKE UPPER.

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

JOB NO. 3409 - 09

 SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
 1/4 IN. SCALE

 1 TIME OF CONCENTRATION  
 2

 3 SCS TR #55 METHOD:  
 4

 5 a) OVERLAND FLOW  
 6

7 LENGTH = 2550 FT  
 8

9 HEAD = 1100 - 740 = 360 FT  
 10

11 Slope =  $\frac{360}{2550} = 0.14 = 14\%$   
 12

 13 FROM FIGURE 3-1, PAGE 3-2  
 14

15 Velocity = 0.9 FT/Sec  
 16

17  $T_c = \frac{2550 \text{ FT}}{0.9 \text{ FT/Sec}} = 2833 \text{ Sec} = 47 \text{ min}$   
 18

 21 b) CHANNEL FLOW  
 22

23 LENGTH = 2750 FT  
 24

25 HEAD = 740 - 540 = 200 FT  
 26

27 Slope =  $\frac{200}{2750} = 0.073 = 7.3\%$   
 28

29 HYDRAULIC RADIUS = 0.83 FT  
 30

 31 (ASSUME A 10'x1' RECTANGULAR CHANNEL)  
 32

 33 USE MANNING'S EQUATION:  
 34

35  $V = \frac{1.49}{n} R^{2/3} S^{1/2}$   
 36

 37 WHERE \*  $n = 0.04$  (FROM "OPEN CHANNEL"  
 38 HYDRAULICS" BY CHOW)

Date 12-2-79Computed 12/12/79Checked FEO

JOB NO. 3409-09

SQUARES  
1/4 IN. SCALE 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

$$V = \frac{1.49}{0.04} (0.83) (0.073)^{\frac{1}{2}} = 8.9 \text{ FT/SEC}$$

$$T_C = \frac{2750 \text{ FT}}{8.9 \text{ FT/SEC}} = 309 \text{ SEC} = 5.1 \text{ MIN}$$

$$\text{TOTAL } T_C = 47 + 5.1 = \underline{\underline{52.1}} \text{ MIN}$$

## 2 - Soil & WATER CONSERVATION ENGINEERING

$$h = 0.6 T_C$$

$$L = \frac{\ell (s+1)^{1.67}}{9000 y^{0.5}}$$

$$s = \frac{1000}{CN} - 10$$

TAKE CN = 20 FOR WOODS

$$s = \frac{1000}{70} - 10 = 4.3$$

$$\ell = 2550 + 2750 = 5300 \text{ FT}$$

$$y = \frac{0.14 + 0.073}{2} = 0.11 = 11\%$$

$$L = \frac{(5300)^{0.8} (4.3+1)^{1.67}}{9000 (11)^{\frac{1}{2}}} = 0.52 \text{ hrs.}$$

$$T_C = \frac{0.52}{0.6} = 0.87 \text{ Hrs} = \underline{\underline{52.2}} \text{ MIN}$$

JOB NO. 3409-09

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
1/4 IN. SCALE

3 - TEXAS HIGHWAY VELOCITY DATA

a) OVERLAND FLOW

$$\text{SLOPE} = 14\%$$

$$\text{AVE. VELOCITY} = 3.5 \text{ FT/SEC}$$

$$T_C = \frac{2550 \text{ FT}}{3.5 \text{ FT/Sec}} = 729 \text{ SEC} = 12 \text{ MIN.}$$

b) CHANNEL FLOW

$$\text{SLOPE} = 7.3\%$$

$$\text{AVE. VELOCITY} = 5 \text{ FT/SEC}$$

$$T_C = \frac{2750 \text{ FT}}{5 \text{ FT/Sec}} = 550 \text{ SEC} = 9.2 \text{ MIN.}$$

$$\text{TOTAL } T_C = 12 + 9.2 = 21.2 \text{ MIN.}$$

4 - KERBY METHOD

a) OVERLAND Flow

$$T_C = 0.83 \left( \frac{NL}{VS} \right)^{0.467}$$

$$L = 2750 \text{ FT}$$

$$N = 0.60$$

$$S = 0.073$$

$$T_C = 0.83 \left[ \frac{(0.6)(2750)}{\sqrt{0.14}} \right]^{0.467}$$

$$T_C = 42 \text{ MIN.}$$

JOB NO. 3409-09

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
1/4 IN. SCALE

1

## 2 b) CHANNEL FLOW

3

4  $V = \frac{1.49}{0.04} (0.83) (0.073)^{2/3} = 8.9 \text{ FT/sec}$

5

6  $T_C = 5.1 \text{ min}$

7

8  $\text{TOTAL } T_C = 42 + 5.1 = \underline{\underline{47.1}} \text{ min}$

9

10

11

12  $\text{AVE. } T_C = \frac{21.2 + 52.2 + 47.1 + 52.1}{4} = 44 \text{ Min}$

13

14

15  $\text{LAG TIME} = 0.6 T_C = 0.6(44) = 26 \text{ Min}$

16

17

18

19  $L = 26 \text{ Min}$

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

JOB NO. 3409-09

SQUARES  
1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

DEVELOPMENT OF RATING CURVE


USE THE WEIR EQUATION  $Q = C L H^{3/2}$  TO  
DEVELOPE A RATING CURVE

\*  $C = 2.6$  FOR WOODED EMBANKMENT

$C = 2.9$  FOR CONCRETE SECTION

\* "C" VALUES WERE TAKEN FROM BRATER & KING  
"HANDBOOK OF HYDRAULICS" PAGE 5-40,  
TABLE 5-3

KANPF E KANPF D A M  
GOETZ PROSS SE ET GOV



ELEVATION FT	SPIKE WAY LENGTH = 80' HEAD (FT)	TOP OF DAM HEAD (FT)	LENGTH (FT)	Q (CFS)	TWO 1-FOOT DIAMETER PIPES * CFS	COMBINE Q CFS
529.5	0	0			0	0
530	0	0			1	1
530.6	0	0			6	6
534	3.4	545			18	563
536	5.4	1092	2	200	1330	18
538	7.4	1751	4	210	4336	18
540	9.4	2507	6	220	8730	18
						11255

\* DISCHARGE VALUES FOR 1-FOOT DIAMETER PIPES WERE TAKEN FROM  
"HYDRAULICS CHARTS FOR THE SELECTION OF HIGHWAY CULVERTS"  
U.S. DEPT. OF TRANSPORTATION, CIRCULAR NO. 5

38  
37  
36  
35  
34  
33  
32  
31  
30  
29  
28  
27  
26  
25  
24  
23  
22  
21  
20  
19  
18  
17  
16  
15  
14  
13  
12  
11  
10  
9  
8  
7  
6  
5  
4  
3  
2  
1

1/4 IN. SCALE


0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
SQUARES

Job No. 3409-09  
Subject: KILLIFEE (N.Y.) - 2011  
Sheet No. 01  
Date 12-3-79  
Compled

3 - 2

Anderson-Nichols & Company, Inc.

DISCHARGE (CFS)



Anderson-Nichols &amp; Company, Inc.

Subject KANIPFE LAKE DAM

Sheet No. \_\_\_\_\_ of \_\_\_\_\_  
 Date 12-5-79  
 Computed 924400  
 Checked FJD

JOB NO. 3409-09

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
 1/4 IN. SCALE

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

ELEVATION (FT)	SURFACE AREA (ac)	AVERAGE S.A. (ac)	INCREMENTAL STORAGE (ac-ft)	CUMULATIVE STORAGE (AC-FT)
530	32	32	192	192
540	49	40.5	405	597
560	147	98	1960	2557

HEC-1 INPUT

ELEV.(NGVD)

STORAGE  
(AC-FT)

516.6

0

529.5

188

530

192

530.6

210

534

300

536


370

538

450

540

597



JOB NO. 3409-09

SQUARES  
1/4 IN SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

1                   DETERMINE TIME OF CONCENTRATION  
 2

3                   OVERLAND FLOW:

5                   LENGTH = 2500 FT

6                   HEAD = 880 - 530 = 350 FT

8                   SLOPE =  $\frac{350}{2500} = 0.14$

11                  1- SCS TR #55 METHOD:

13                  FROM FIG. 3-1, PAGE 3-2 USING FOREST  
 14                  WITH HEAVY GROUND LITTER & MEADOW

16                  VELOCITY = 0.9 FT/SEC

18                   $T_c = \frac{2500 \text{ FT}}{0.9 \text{ FT/SEC}} = 2778 \text{ SEC} = 46 \text{ MIN}$

22                  2- Soil & WATER CONSERVATION ENGINEERING METHOD:

24                   $L = 0.6 T_c$

26                   $L = \frac{\ell^{0.8} (S+1)^{1.67}}{9000 y^{0.5}}$

28                   $S = \frac{1000}{CN} - 10$

30                  TAKE CN=70 FOR WOODS

32                   $S = \frac{1000}{70} - 10 = 4.3$

34                   $\ell = 2500 \text{ FT}$

35                   $y = 0.14 = 14\%$

JOB NO. 3409-09

SQUARES  
1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

$$L = \frac{(2500)^{0.8} (4.3+1)^{1.67}}{9000 (14)^{0.5}} = 0.25 \text{ hrs}$$

$$T_c = \frac{0.25}{0.6} = 0.42 \text{ hrs} = 25 \text{ min}$$

### 3 - TEXAS HIGHWAY VELOCITY DATA (DESIGN OF SMALL DAMS)

SLOPE = 14%

VELOCITY = 3.5 FT/SEC

$$T_c = \frac{2500 \text{ FT}}{3.5 \text{ FT/sec}} = 714 \text{ sec} = 12 \text{ min}$$

### 4 - KERBY METHOD:

$$T_c = 0.83 \left( \frac{NL}{\sqrt{S}} \right)^{0.467}$$

L = 2500 FT

N = 0.60

S = 0.14

$$T_c = 0.83 \left( \frac{(0.6)(2500)}{\sqrt{0.14}} \right)^{0.467} = 40 \text{ min}$$

$$\text{AVERAGE } T_c = \frac{46+25+12+40}{4} = 31 \text{ min}$$

$$L = \text{LAG TIME} = 0.6 T_c = 0.6 (31)$$

$$L = 19 \text{ min}$$

JOB NO. 3409 - 09

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
1/4 IN. SCALE

1

2

3

D/S HAZARD:

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

STAR LAKE LOWER IS LOCATED JUST D/S OF STAR LAKE UPPER DAM. CAMPING AREA AND BUILDINGS ARE LOCATED D/S OF STAR LAKE LOWER DAM. ALL STRUCTURES ARE LOCATED BELOW THE WATER SURFACE ELEV. AT STAR LAKE LOWER. A BREACH ANALYSIS WAS CONDUCTED USING HEC-I COMPUTER PROGRAM TO DETERMINE THE EFFECT OF STAR LAKE UPPER DAM BREACH ON STAR LAKE LOWER DAM AND THE STRUCTURES LOCATED JUST D/S OF IT.



Mapped by the Army Map Service

Edited and published by the Geological Survey

Cooperative USGS and New York State Geological Survey

Series 1: 1967

Fig. 16

JOB NO. 3409-9

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
1/4 IN. SCALE

1

2

DEVELOPMENT OF RATING CURVE

3

## 4 - SPILLWAY CURVE:

5

6

a) COMPUTE Q USING WEIR EQUATION  
 $(Q = C L H^{3/2})$  UP TO LOW CHORD OF  
THE BRIDGE \*C = 2.9.

7

8

b) FROM 532.6' ELEV. USE ORIFICE FLOW FOR  
BRIDGE OPENING (\*C = 0.82), AND WEIR  
FLOW OVER THE BRIDGE (\*C = 2.3 IS USED  
TO ACCOUNT FOR LOSSES DUE TO THE BRIDGE)

9

10

## 11 - TOP OF DAM CURVE:

12

13

14 COMPUTE Q USING WEIR EQUATION

15

16  $Q = C L H^{3/2}$  WHERE \*C = 2.7

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

\* "C" VALUES WERE TAKEN FROM BRAUER & KING  
"HANDBOOK" OF HYDRAULICS

33

34

35

36

37

38

ELEV (FT)	WEIR FLOW Q	ORIFICE FLOW Q	FLOW OVER BRIDGE Q	COMBINED HEAD Q	TOP OF HEAD (FT)	LENGTH (FT)	COMBINED Q (CFS)
529.9	0	0	-	0	-	-	0
531	1.1	174	-	174	-	-	174
531.6	1.7	334	-	334	-	-	334
532.1	2.2	492	-	492	0.5	149	629
532.6	-	1.35	670	-	670	1.35	1430
533.7	-	2.45	980	1.1	138	1.95	3245
535	-	3.65	990	3.4	750	3.25	3360

\* LENGTH OF SPILLWAY = 52 FEET

38

37

36

35

34

33

32

31

30

29

28

27

26

25

24

23

22

21

20

19

18

17

16

15

14

13

12

11

10

9

8

7

6

5

4

3

2

1

1/4 IN. SCALE  
SQUARES

JOB NO.

Anderson-Nichols & Company, Inc.

Subject

Sheet No.

Date

Computed


Checked

of

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

COMPUTED: MINM  
CKD : TDD

0041 300 200 100 0 DISTANCE (FT.)




NO. 5124. 10 DIVISIONS PER INCH BOTH WAYS AND 10 DIVISIONS

© 1947 BY THE ROCKWELL PHONOCO & BOOK CO., NEW YORK, N.Y.  
GRAPH PAPER

### DISCHARGE (CFS)

8000  
6000  
4000  
2000  
0

STAIR LAKE UPPER DAM  
RATING CURVE



ELEV.  
532  
531  
530  
3 - 19

## **Anderson-Nichols & Company, Inc.**

Subject STAR LAKE UPPER DAM

Sheet No. \_\_\_\_\_ of \_\_\_\_\_  
Date 12 - 7-79  
Computed 12/1/01  
Checked FDP

JOB NO. 3409-09

**SQUARES**    0    1    2    3    4    5    6    7    8    9    10    11    12    13    14    15    16    17    18    19    20    21    22    23    24    25    26    27    28    29    30  
**1/4 IN. SCALE**

## STORAGE-ELEVATION DETERMINATION

MAXIMUM DEPTH = 8.3 FT

AVERAGE DEPTH = 7 FT

NORMAL POOL STORAGE = 115 AC-FT


ELEVATION FT MSL	SURFACE AREA (ACRES)	AVERAGE S. A. (AC.)	INCREMENTAL STORAGE AC-FT	CUMULATIVE STORAGE AC-FT
530	16.5	16.5	115	115
540	28	22.2	222	337
560	30	29	580	917

## INPUT FOR HEC1

	ELEV. (FT MSL)	STORAGE (AC-FT)
24		
25	521.5	0
26	529.9	115
27		
28	531	136
29		
30	531.6	150
31	532.1	165
32	532.6	172
33	533.7	197
34	535	225

COMPUTED: 1.1114  
OKD · FDD

## STAR LAKE OPERATOR'S STORM PREPARATION



$\frac{1}{2} FV$  :  $(\bar{F}_7 MSL)_{650}$

3-21

NO. 31,282. IN DIVISION FIFTH CLASS BOTH WAYS.  
NUMBERED 1 TO 100.

© CROWN IN STOCK UNLESS PRINTED ON DARKER PAPER. NO REPRODUCTION, WHOLE OR PART, IS PERMITTED.  
GRAPH PAPER

" RATING CURVE FOR STAR LAKE LOWER "

ELEV. (FT)	LEFT SPILLWAY		RIGHT SPILLWAY		TOP OF DAM HEAD (FT)	HEAD (CFS)	LENGTH (FT)	TOP OF DAM HEAD (CFS)	COMBINED Q (CFS)
	L = 20 FT HEAD (FT)	Q (CFS)	L = 26 FT HEAD (FT)	Q (CFS)					
524.1	0	0	0	0				0	
524.2	0.1	2	0	0				2	
525.3	1.2	76	1.1	87	0			163	
526	1.9	152	1.8	182	0.7	50	76	410	
526.2	2.1	140	2	169	0.3	386	165	475	
527	2.9	227	2.8	280	-	-	1562	2070	

- a) UP TO THE LOW CHORD OF THE BRIDGE USE WEIR EQUATION ( $C = 2.9$ )  
 b) FROM LOW CHORD UP USE WEIR EQUATION WITH ( $C = 2.3$ ) TO ACCOUNT  
 FOR LOSSES DUE TO THE BRIDGE  
 c)  $C = 2.6$  FOR DIRT ROAD
- \* " C " VALUES WERE TAKEN FROM BRATER & KING " HANDBOOK OF HYDRAULICS "

3-22

JOB NO. 3401-0

Subject: STAR LAKE / PFEF DAM

1/4 IN. SCALE  
SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
Sheet No. 2 - 4 - 74  
Dots 01  
Compled 01  
Checked 01  
01

Anderson-Nichols & Company, Inc.

NO. 5122882. NO DIVISIONS PER INCH BOTH WAYS. NO NO DIVISIONS.

(CONT'D) IN INCHES FROM LEFT EDGE OF DRAWING TO CENTER OF DIVISIONS IN INCHES

0

DISTANCE ( FT )

515

200

240

120

518


520


522

524

526  
H.V. H  
H.S.L  
8-23

520





527

626  
EV.  
115L

3-24

CHARTER PAPER

Anderson-Nichols &amp; Company, Inc.

Subject STAR LAKE UPPER

Sheet No. \_\_\_\_\_ of \_\_\_\_\_  
 Date 12-4-79  
 Computed RALM  
 Checked FDD

JOB NO. 3409-09

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
 1/4 IN. SCALE

2 ELEV. - STORAGE DETERMINATION FOR STAR LAKE LOWER

4 MAXIMUM DEPTH OF LAKE = 17'  
 5 AVERAGE DEPTH OF LAKE = 9'

ELEV. FT MSL	SURFACE AREA (AC)	AVERAGE S. A. 1 AC 1	INCREMENTAL STORAGE AC - FT	CUMULATIVE STORAGE AC - FT
524.1	5.5	5.5	50	50
540	7	6.25	56	106
560	8	7.5	67.5	173.5

18 INPUT FOR HEC1

ELEV.	STORAGE
509 FT MSL	0 AC-FT
524.1	50
524.2	52
525.3	54
526	56
526.2	57
527	60

STORAGE (AC-FT)

180

150

100

50


0

STORAGE - ELEV. CURVE

MARSHAL

E-26

11-17  
11-17  
11-17



JOB NO. 3409 - 09

SQUARES  
1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

D/S HAZARD ANALYSIS:

D/S HAZARD OF STAR LAKE UPPER DAM  
CONSISTS OF STAR LAKE LOWER DAM AND  
THREE STRUCTURES WHICH ARE LOCATED  
JUST D/S OF STAR LAKE LOWER DAM.

STAR LAKE LOWER DAM (TOP OF DAM)	525.3'
BAND STAND BUILDING	523.7'
BUILDING NO. 1	521.4'
BUILDING NO. 2	518.3'

IN CASE OF BREACH OF STAR LAKE UPPER DAM,  
STAR LAKE LOWER DAM COULD BE OVERTOPPED  
BY 106 FEET AND THE STRUCTURES COULD BE  
SEVERELY DAMAGED BY BREACH WAVE. POSSIBILITY  
OF LOSS OF LIFE EXISTS IF THE CAMPGROUND  
IS BEING USED.

JOB NO. 3409-09

 SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
 1/4 IN SCALE

 1 DETERMINATION OF 'C' FOR LOW LEVEL OUTLETS

## 2 1- RIGHT LOW LEVEL OUTLET:

3  $D = \text{DIAMETER} = 18'' = 1.5'$

4  $N = 0.015 (\text{SOIL \& WATER CONSERVATION ENGINEERING})$

5  $A_p = \text{AREA OF PIPE OPENING} = 1.8 \text{ FT}^2$

6  $L_p = \text{LENGTH OF PIPE} = 25 \text{ FT}$

7  $K_f = \text{FRICTION LOSS THROUGH PIPE}$

8  $K_e = \text{ENTRANCE LOSS OF PIPE} = 0.78 (\text{IBID P. 639})$

9  $C_p = \text{COEFFICIENT OF DISCHARGE (INCORPORATING } A_p \text{ \& } 2g)$

10  $C = \text{COEFFICIENT OF DISCHARGE}$

11  $K_f = \frac{5087 m^2}{D^{4/3}}$

12  $C_p = A_p \sqrt{\frac{2g}{1 + K_e + K_f L_p}}$

13  $C = \frac{C_p / A_p}{\sqrt{2g}}$

14  $K_f = \frac{5087 (0.015)^2}{(18)^{4/3}} = 0.024$

15  $C_p = 1.8 \sqrt{\frac{64.4}{1 + 0.78 + (0.024)(25)}} = \frac{9.4}{-}$

16  $C = \frac{9.4 / 1.8}{\sqrt{64.4}} = \underline{0.65}$

## 17 2- LEFT LOW LEVEL OUTLET:

18  $D = 1.5'$

19  $L_p = 12'$

Anderson-Nichols & Company, Inc.

Subject STAR LAKE UPPER DAM

Sheet No. \_\_\_\_\_ of \_\_\_\_\_  
Date 12-6-79  
Computed 820602  
Checked FDD

JOB NO. 3409-09

SQUARES  
1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

1  
2  
3  $K_f = 0.024$

4  $C_p = 1.8 \sqrt{\frac{64.4}{1 + 0.78 + (0.024)(12)}} = 10$

5  
6  
7  
8  $C = \frac{10/1.8}{\sqrt{64.4}} = 0.69$

JOB NO. 3409-09

 SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
 1/4 IN SCALE

 1 DRAWDOWN CALCULATIONS  
 2


 3 CALCULATIONS ASSUME:  
 4


- 5
- 
- 6 1 - NO SIGNIFICANT INFLOW
- 
- 7 2 - LOW LEVEL OUTLETS TO BE OPERABLE
- 
- 8 3 - INVERT U/S SAME AS INVERT AT GATE (526.5')
- 
- 9 4 -
- $Q_p = C_p H^{1/2}$
- 
- 10 5 - AC-FT-DAY = 1.9835 (AVG. Q)
- 
- 11 6 - DAYS =
- $\Delta \text{STORAGE} / \text{AC-FT-DAY}$
- 
- 12 7 -
- $Q_1$
- &
- $Q_2$
- ARE RIGHT AND LEFT LOW-LEVEL OUTLETS DISCHARGE

ELEV. FT	STORAGE AC-FT	$\Delta$ STORAGE AC-FT	H FT	$Q_1$ CFS	$Q_2$ CFS	$Q_{\text{TOTAL}}$ CFS	AVE. Q CFS	AC-FT PER DAY	DAY
529.9	115	20	3.4	17.3	18.4	35.7	31.5	62.5	0.32
528.5	95	7	2	13.3	14	27.3	25.5	50.6	0.14
528	88	8	1.5	11.5	12.2	23.7	21.5	42.6	0.19
527.5	80	7	1.0	9.4	10	19.4	16.5	32.7	0.21
527	73	8	0.5	6.6	7.1	13.7	6.8	13.5	0.6
526.5	65	0	0	0	0	0			

 28 1.5  
 29 DAYS  
 30  
 31  
 32  
 33  
 34  
 35  
 36  
 37  
 38

COMPUTED: MNM  
CKD: FDD





NATIONAL PROGRAM OF INSPECTION OF  
NON-FED. DAMS


STAR LAKE UPPER DAM  
BOROUGH OF BLOOMINGDALE, NEW JERSEY  
REGIONAL VICINITY MAP  
JANUARY 1980

DEPARTMENT OF THE ARMY  
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
PHILADELPHIA, PENNSYLVANIA

ANCERSON-NICHOLS & CO., INC.

CONCORD, NH

SCALE IN MILES



MAP BASED ON U.S.G.S. 7.5 MINUTE QUADRANGLE  
SHEET, WANAQUE, N.J. 1954

HEC-1 OUTPUT  
OVERTOPPING AND BREACH ANALYSIS

STAR LAKE UPPER DAM



47

46

51	Y5	0	2	163	410	475	2070
52	15	0	50	52	54	56	60
53	15	519	524.1	524.2	525.3	526	526.2
54	11	526.1					527
55	SD	525.3					
56	K	99					

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

```
RUNOFF HYDROGRAPH AT A1  
ROUTE HYDROGRAPH TO A2  
RUNOFF HYDROGRAPH AT A2  
ROUTE HYDROGRAPH AT A3  
COMBINE 2 HYDROGRAPHS AT A4  
ROUTE HYDROGRAPH TO A5  
ROUTE HYDROGRAPH TO A6  
END OF NETWORK
```

FLOOD HYDROGRAPH PACKAGE (HEC-1)  
DAM SAFETY VERSION      JULY 1979  
LAST MODIFICATION 26 FEB 79

RUN DATE: 7/12/06.  
TIME: 07:39:24.

STAR LAKE UPPER DAM OVERTOPPING ANALYSIS M. PIREMADI ANDERSON-NICHOLS  
DAM NUMBER NJ0022-52

0.1 0.25 0.5 MULTIPLES OF 24 HOUR PMP

JOB SPECIFICATION							
NG	NHR	AMIN	IDAY	IHR	IMIN	METRC	JPLT
170	0	10	0	0	0	0	0
						LROFT	TRAC
						0	0

MULTI-PLAN ANALYSES TO BE PERFORMED

P1105= .10    .25    .50

SUB-AREA RUNOFF COMPUTATION

DEVELOP INFLOW HYDROGRAPH FOR KAMPF LAKE

ISTAO	ICOMP	IECON	ITAPE	JPLT	JPRTR	I NAME	I STAGE	I AUTO
A1	0	0	0	0	0	0	0	0

HYDROGRAPH DATA

HYDGI	IUHG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOV	ISAME	LOCAL
1	2	.86	0.00	.86	.86	0.000	0	1	0

PRECIP DATA

SPFT	PMS	R6	R12	R24	R48	R72	R96
0.00	22.00	111.00	123.00	133.00	0.00	0.00	0.00

LOSS DATA							
TROPT	STRK	DLTKR	RTOL	FRAIN	STRKS	RT10K	STRIL
0	0.00	0.00	1.00	0.00	0.00	1.00	0.10
							0.00

UNIT HYDROGRAPH DATA

TC= 0.00    LAG= .43

PERCESSION DATA

ST10= -3.00    ORCSN= 0.00    RT10R= 1.00  
UNIT HYDROGRAPH IS END OF FLIGHT ORDINATES. TC= 0.00 HOURS, LAG= 0.03 VOL= 1.00  
17A. 599. 700. 694. 435. 20P. 150. PT. 52. 1. 1P. 7. a.

FLUD-OF-PPRPTOR FLOW

	PC.DA	HR.PN	PER100	RAIN	EXCS	LOSS	COMP Q	PO.DA	HR.PN	PER100	RAIN	EYES	LOSS	COMP Q
1.01	.10	1	.02	.00	.02	.02		1.01	14.20	.06	.49	.47	.02	1315.
1.01	.20	2	.02	.00	.02	.02		1.01	14.30	.07	.49	.47	.02	1398.
1.01	.30	3	.02	.00	.02	.02		1.01	14.40	.08	.49	.47	.02	1460.
1.01	.40	4	.02	.00	.02	.02		1.01	14.50	.09	.49	.47	.02	1512.
1.01	.50	5	.02	.00	.02	.02		1.01	15.00	.09	.49	.47	.02	1537.
1.01	.60	6	.02	.00	.02	.02		1.01	15.10	.01	.45	.43	.02	1544.
1.01	.70	7	.02	.00	.02	.02		1.01	15.20	.02	.45	.43	.02	1580.
1.01	.80	8	.02	.00	.02	.02		1.01	15.30	.03	.34	.32	.02	1P31.
1.01	.90	9	.02	.00	.02	.02		1.01	15.40	.04	.34	.32	.02	2761.
1.01	1.00	10	.02	.00	.02	.02		1.01	15.50	.05	.97	.95	.02	420.
1.01	1.10	11	.02	.00	.02	.02		1.01	16.00	.06	.59	.58	.02	4876.
1.01	2.00	12	.02	.00	.02	.02		1.01	16.10	.07	.46	.44	.02	4435.
1.01	2.10	13	.02	.00	.02	.02		1.01	16.20	.08	.46	.44	.02	3452.
1.01	2.20	14	.02	.00	.02	.02		1.01	16.30	.09	.46	.44	.02	2657.
1.01	2.30	15	.02	.00	.02	.02		1.01	16.40	.00	.46	.44	.02	2177.
1.01	2.40	16	.02	.00	.02	.02		1.01	16.50	.01	.46	.44	.02	1660.
1.01	2.50	17	.02	.00	.02	.02		1.01	17.00	.02	.46	.44	.02	1710.
1.01	3.00	18	.02	.00	.02	.02		1.01	17.10	.03	.36	.34	.02	1592.
1.01	3.10	19	.02	.00	.02	.02		1.01	17.20	.04	.36	.34	.02	1474.
1.01	3.20	20	.02	.00	.02	.02		1.01	17.30	.05	.36	.34	.02	1360.
1.01	3.30	21	.02	.00	.02	.02		1.01	17.40	.06	.36	.34	.02	1272.
1.01	3.40	22	.02	.00	.02	.02		1.01	17.50	.07	.36	.34	.02	1215.
1.01	3.50	23	.02	.00	.02	.02		1.01	18.00	.08	.36	.34	.02	1180.
1.01	4.00	24	.02	.00	.02	.02		1.01	18.10	.09	.03	.01	.02	1102.
1.01	4.10	25	.02	.00	.02	.02		1.01	18.20	.10	.03	.01	.02	1095.
1.01	4.20	26	.02	.00	.02	.02		1.01	18.30	.11	.03	.01	.02	624.
1.01	4.30	27	.02	.00	.02	.02		1.01	18.40	.12	.03	.01	.02	392.
1.01	4.40	28	.02	.00	.02	.02		1.01	18.50	.13	.03	.01	.02	277.
1.01	4.50	29	.02	.00	.02	.02		1.01	19.00	.14	.03	.01	.02	164.
1.01	5.00	30	.02	.00	.02	.02		1.01	19.10	.15	.03	.01	.02	114.
1.01	5.10	31	.02	.00	.02	.02		1.01	19.20	.16	.03	.01	.02	85.
1.01	5.20	32	.02	.00	.02	.02		1.01	19.30	.17	.03	.01	.02	6R.
1.01	5.30	33	.02	.00	.02	.02		1.01	19.40	.18	.03	.01	.02	5R.
1.01	5.40	34	.02	.00	.02	.02		1.01	19.50	.19	.03	.01	.02	52.
1.01	5.50	35	.02	.00	.02	.02		1.01	20.00	.20	.03	.01	.02	47.
1.01	6.00	36	.02	.00	.02	.02		1.01	20.20	.21	.03	.01	.02	45.
1.01	6.10	37	.02	.00	.02	.02		1.01	20.30	.22	.03	.01	.02	45.
1.01	6.20	38	.02	.00	.02	.02		1.01	20.40	.24	.03	.01	.02	45.
1.01	6.30	39	.02	.00	.02	.02		1.01	20.50	.25	.03	.01	.02	45.
1.01	6.40	40	.02	.00	.02	.02		1.01	21.00	.26	.03	.01	.02	45.
1.01	6.50	41	.02	.00	.02	.02		1.01	21.10	.27	.03	.01	.02	45.
1.01	7.00	42	.02	.00	.02	.02		1.01	21.20	.28	.03	.01	.02	45.
1.01	7.10	43	.02	.00	.02	.02		1.01	21.30	.29	.03	.01	.02	45.
1.01	7.20	44	.02	.00	.02	.02		1.01	21.40	.30	.03	.01	.02	45.
1.01	7.30	45	.02	.00	.02	.02		1.01	21.50	.31	.03	.01	.02	45.
1.01	7.40	46	.02	.00	.02	.02		1.01	21.60	.32	.03	.01	.02	45.
1.01	7.50	47	.02	.00	.02	.02		1.01	22.00	.32	.03	.01	.02	45.
1.01	8.00	48	.02	.00	.02	.02		1.01	22.10	.33	.03	.01	.02	45.
1.01	8.10	49	.02	.00	.02	.02		1.01	22.20	.34	.03	.01	.02	45.
1.01	8.20	50	.02	.00	.02	.02		1.01	22.30	.35	.03	.01	.02	45.
1.01	8.30	51	.02	.00	.02	.02		1.01	22.40	.36	.03	.01	.02	45.
1.01	8.40	52	.02	.00	.02	.02		1.01	22.50	.37	.03	.01	.02	45.
1.01	8.50	53	.02	.00	.02	.02		1.01	23.00	.38	.03	.01	.02	45.
1.01	9.00	54	.02	.00	.02	.02		1.01	23.10	.39	.03	.01	.02	45.
1.01	9.10	55	.02	.00	.02	.02		1.01	23.20	.40	.03	.01	.02	45.
1.01	9.20	56	.02	.00	.02	.02		1.01	23.30	.41	.03	.01	.02	45.
1.01	9.30	57	.02	.00	.02	.02		1.01	23.40	.42	.03	.01	.02	45.
1.01	9.40	58	.02	.00	.02	.02		1.01	23.50	.43	.03	.01	.02	45.

VOLUME 2002

	PEAK CFS	6-HOUR CFS	24-HOUR CFS	72-HOUR CFS	TOTAL VOLUME
CMS	9876.	1711.	481.	408.	69303.
INCHES	13.0.	4.0.	1.4.	1.2.	1962.
AC-F1		10.50	20.80	20.82	20.82
THOUS CFS		469.96	528.41	528.91	528.91
		848.	950.	955.	955.
		1046.	1176.	1177.	1177.

**HYDROGRAPH AT STA. 1 FOR PLAN I, RIO**

PEAK	6-110UR	24-HOUR	72-HOUR	TOTAL
2019	85.5	20.0	0.0	105.5
2020	85.5	20.0	0.0	105.5
2021	85.5	20.0	0.0	105.5
2022	85.5	20.0	0.0	105.5

CRS	69.	24.	7.	6.	961.
INCHES		9.25	10.40	10.41	10.41
M	234.90	264.21	264.45		264.45
AC-FY	424.	477.	477.		477.
THOUS CU M	523.	589.			589.

PLAN 2 SAME AS PLAN 1

#### HYDROGRAPH ROUTING

#### ROUTE INFLOW HYDROGRAPH THROUGH KÄMPFÉ LAKE RESERVOIR

ISTAG	JCOMP	IECON	ITAPE	JPLT	JPT	I NAME	I STAGE	I AUTO
A2	1	0	0	0	0	1	1	0

ALL PLANS HAVE SAME

QLOSS	CLOSS	Avg	IRES	ISAMT	IOPF	IPMP	LSTR
0.0	0.000	0.00	1	1	0	0	0

NSTPS	NSTDL	LAG	AMSKK	X	TSK	STORA	ISPRAT
1	0	0	0.000	0.000	0.000	210.	-1

STAGF	529.50	530.00	530.60	534.00	536.00	538.00	540.00
-------	--------	--------	--------	--------	--------	--------	--------

FLOW	0.00	1.00	6.00	563.00	2640.00	6305.00	11255.00
------	------	------	------	--------	---------	---------	----------

CAPACITY	0.	1.00.	192.	210.	300.	370.	450.
----------	----	-------	------	------	------	------	------

F ELEVATION=	517.	530.	531.	534.	536.	538.	540.
--------------	------	------	------	------	------	------	------

CREL	SPVID	COOV	EXPV	ELEV	COOL	CAREA	EXPL
530.6	0.0	0.0	0.0	0.0	0.0	0.0	0.0

#### DAM DATA

TOPFL	CODD	EXPO	DAMVID
534.0	0.0	0.0	0.

### **END-OF-PERIOD HYDROGRAPH ORDINATES STATION A2, PLAN 1, RATIO 3**

STATION NUMBER ONE IS 1010: 1111ST 16611 HOURS

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
CFS	1830.	758.	239.	204.	34621.	
CMS	52.	21.	7.	6.	980.	
INCHES	MM	8.20	10.36	10.40	10.40	
AC-FT	MM	208.36	263.12	264.22	264.22	
THOUS CUM	MM	376.	475.	477.	477.	
		464.	586.	586.	586.	

**STATION A20. PLAN 2. RATIO 3  
END-OF-PERIOD HYDROGRAPH COORDINATES**

6.0 6.0 6.0 6.0 6.0 6.0

卷之三

PERIOD	5-MINUTE	24-HOUR	72-HOUR	FINAL VOLUME
CFS	103.0	75.0	20.0	34521.0
CPS	5.2	2.1	.7	99.0
CPM	—	—	—	—





1.01	12.40	76.	.33	.31	.02	247.	1.02	2.50	161	0.00	0.00	0.00
1.01	12.50	77.	.33	.31	.02	267.	1.02	3.00	162	0.00	0.00	0.00
1.01	13.00	78.	.33	.31	.02	277.	1.02	3.10	163	0.00	0.00	0.00
1.01	13.10	79.	.39	.37	.02	286.	1.02	3.20	164	0.00	0.00	0.00
1.01	13.20	80.	.39	.37	.02	309.	1.02	3.30	165	0.00	0.00	0.00
1.01	13.30	81.	.39	.37	.02	328.	1.02	3.40	166	0.00	0.00	0.00
1.01	13.40	82.	.39	.37	.02	338.	1.02	3.50	167	0.00	0.00	0.00
1.01	13.50	83.	.39	.37	.02	343.	1.02	4.00	168	0.00	0.00	0.00
1.01	13.60	84.	.39	.37	.02	345.	1.02	4.10	169	0.00	0.00	0.00
1.01	13.70	85.	.39	.37	.02	356.	1.02	4.20	170	0.00	0.00	0.00
									SUM	23.41	20.62	2.72
									( 595.) ( 526.) ( 69.) ( 548.02 )			19353.

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	1522.	480.	134.	114.	19346.
CMS	43.	14.	4.	3.	548.
INCHES		18.59	20.80	20.82	20.82
"M		472.20	528.41	528.91	528.91
AC-FT		238.	266.	266.	
THOUS CU M		293.	320.	329.	329.

HYDROGRAPH AT STA A3 FOR PLAN 1, RATIO 3									
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	2.	8.	15.	17.	18.	19.	19.	20.	20.
20.	20.	20.	20.	20.	20.	20.	20.	20.	20.
20.	20.	20.	20.	20.	20.	20.	20.	20.	20.
20.	20.	33.	69.	104.	124.	134.	139.	144.	155.
164.	169.	172.	173.	178.	192.	205.	212.	216.	216.
216.	225.	269.	502.	761.	733.	590.	386.	298.	252.
	229.	217.	206.	169.	174.	166.	163.	161.	144.
	55.	31.	19.	13.	9.	8.	7.	6.	6.
	6.	6.	6.	6.	6.	6.	6.	6.	6.
	6.	6.	6.	6.	6.	6.	6.	6.	6.
	6.	6.	6.	6.	6.	6.	6.	6.	6.
	0.	0.	0.	0.	0.	0.	0.	0.	0.
	0.	0.	0.	0.	0.	0.	0.	0.	0.

PLAN 2 SAME AS PLAN 1

COMBINE HYDROGRAPHS

COMBINE A2 AND A3 HYDROGRAPHS

## SUM OF 2 HYDROGRAPHS AT

PLAN 1

RATIO 3

6.	6.	6.	6.	6.	6.	6.	6.	6.
6.	6.	6.	6.	6.	6.	6.	6.	6.
6.	6.	6.	6.	6.	6.	6.	6.	6.
6.	6.	6.	6.	6.	6.	6.	6.	6.
6.	6.	6.	6.	6.	6.	6.	6.	6.
6.	8.	13.	19.	22.	24.	25.	29.	34.
43.	47.	50.	54.	57.	59.	62.	64.	67.
70.	72.	74.	75.	76.	78.	79.	80.	81.
82.	83.	97.	140.	188.	227.	262.	293.	326.
359.	432.	461.	486.	518.	557.	595.	629.	660.
711.	743.	836.	1197.	1811.	2198.	2297.	2216.	1804.
1596.	1426.	1285.	1162.	1057.	973.	967.	856.	797.
609.	561.	518.	479.	444.	411.	380.	352.	325.
279.	259.	240.	223.	207.	192.	179.	167.	155.
135.	127.	119.	111.	105.	98.	93.	87.	78.
74.	70.	67.	64.	60.	56.	51.	47.	43.
37.	34.	31.	29.	27.	25.	23.	21.	19.
17.	15.	14.	13.	12.	11.	11.	10.	9.

## PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

CFS 2297. 973. 307. 261. 94292.

CPS 65. 28. 9. 7. 1254.

INCHES 8.23 10.37 10.40 10.40

MM 209.05 263.36 264.27 264.27

AC-FT 483. 608. 610. 610.

THOUS CU M 595. 750. 753. 753.

AD-A087 536

NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON  
NATIONAL DAM SAFETY PROGRAM, STAR LAKE UPPER DAM (NJ00221), DEL--ETC(U)  
FEB 80 W GUINAN

F/G 13/13

DACW61-79-C-0011

NL

UNCLASSIFIED

2 OF 2

AD-A087 536

END

DATE

FILED

9-80

DTC

	SUM OF 2 HYDROGRAPHS AT			A9	PLAN 2	PLAN 3	
	6*	6*	6*	6*	6*	6*	6*
6*	6*	6*	6*	6*	6*	6*	6*
6*	6*	6*	6*	6*	6*	6*	6*
6*	6*	6*	6*	6*	6*	6*	6*
6*	6*	6*	6*	6*	6*	6*	6*
6*	6*	6*	6*	6*	6*	6*	6*
43	47	50	54	57	59	62	64
70	72	74	75	76	78	79	80
82	83	97	140	188	227	262	293
39%	432	461	488	518	557	595	629
711	743	834	1197	1811	2198	2297	2216
1598	1426	1285	1162	1057	973	907	856
609	561	510	479	444	411	380	352
279	259	240	223	207	192	179	167
135	127	119	111	105	98	93	87
74	70	67	64	60	56	51	47
37	34	31	29	27	25	23	21
17	15	14	13	12	11	11	10
							9.
PEAK	2297	973	307	24-HOUR	72-HOUR	TOTAL VOLUME	
CFS	65.	28.	9.			44292.	
CMS		8.23	10.17			1254.	
INCHES						10.40	
INCHES							
AC-FT		263.36	264.27			264.27	
AC-FT		483.	610.			610.	
THOUS CU M		608.	750.			753.	

۲۶

THE HAWAIIAN

LAKE SUPERIOR

```

    .TSTAO 1CCMP 1ECON 1TAFF 1PLT 1PRJ 1NAME 1STAGE .TAUTO
    A5      1      0      0      0      0      0      1      0      0

```

ALL BIRDS HAVE FEET

ROUTING DATA

**c** **c** **c** **c** **c** **c** **c** **c** **c** **c**

NSIPS NSIDI LAS ANSEK X X ISK SIORA ISPRAT

卷之三

**531.00**      **331.60**      **532.10**      **532.60**      **533.70**      **535.00**

**174.00**      **334.00**      **629.00**      **1413.00**      **3245.00**      **7360.00**

1150 1360 1500 1650 1720 1970 2250

卷之三

卷之三

ECONOMIC DATA

卷之三

卷之三

CERVIDO Z CLAM TRAIL USEL FARELL

卷之三

SILATION ELEMEN T, MUL TI 1

END-OF-PERIOD HYDROGRAPH ORDINATES


CUTFLOW

THE DAM-PREACH HYDROGRAPH WAS DEVELOPED USING A TIME INTERVAL OF .021 HOURS DURING BREACH FORMATION.  
 MUNSTRAUP CALCULATIONS WILL USE A TIME INTERVAL OF .167 HOURS.  
 THIS TABLE COMPARES THE HYDROGRAPH FOR DOWNSTREAM CALCULATIONS WITH THE COMPUTED-BREACH HYDROGRAPH.  
 INTERMEDIATE FLOWS ARE INTERPOLATED FROM END-OF-PERIOD VALUES.

TIME (HOURS)	INTERPOLATED BEGINNING OF BREACH (OURS)	INTERPOLATED BREACH HYDROGRAPH (CFS)	COMPUTED BREACH HYDROGRAPH (CFS)		ACCUMULATED ERROR (CFS)	ACCUMULATED ERROR (AC-Ft)
			BREACH	HYDROGRAPH		
15.833	0.000	376.	376.	0.	0.	0.
15.854	.021	397.	392.	5.	5.	0.
15.875	.042	419.	411.	11.	13.	0.
15.896	.063	440.	431.	9.	22.	0.
15.917	.083	461.	452.	6.	32.	0.
15.938	.104	482.	474.	6.	40.	0.
15.958	.125	504.	497.	6.	47.	0.
15.979	.146	525.	521.	4.	50.	0.
16.000	.167	546.	546.	0.	50.	0.
16.021	.188	572.	571.	0.	50.	0.
16.042	.209	598.	597.	0.	51.	0.
16.063	.229	623.	623.	0.	51.	0.
16.083	.250	649.	648.	1.	52.	0.
16.104	.271	675.	670.	1.	53.	0.
16.125	.292	700.	699.	1.	54.	0.
16.146	.313	726.	725.	1.	55.	0.
16.167	.333	752.	752.	0.	55.	0.
16.188	.354	778.	778.	0.	55.	0.
16.208	.375	805.	805.	-1.	54.	0.
16.229	.396	831.	832.	-1.	53.	0.
16.250	.417	857.	859.	-2.	51.	0.
16.271	.438	884.	885.	-2.	49.	0.
16.292	.458	910.	911.	-1.	48.	0.
16.313	.479	937.	937.	-1.	47.	0.
16.333	.500	963.	963.	0.	47.	0.
16.354	.521	988.	989.	-1.	46.	0.
16.375	.542	1013.	1014.	-1.	46.	0.
16.376	.563	1038.	1039.	-1.	45.	0.
16.417	.583	1063.	1065.	-1.	44.	0.
16.438	.604	1088.	1090.	-1.	42.	0.
16.458	.625	1113.	1115.	-1.	41.	0.
16.479	.646	1139.	1139.	-1.	41.	0.
16.500	.667	1164.	1164.	-0.	41.	0.
16.521	.688	1192.	1192.	-3.	45.	0.
16.542	.708	1220.	1219.	2.	46.	0.
16.563	.729	1248.	1247.	1.	46.	0.
16.583	.750	1276.	1276.	0.	47.	0.
16.604	.771	1304.	1305.	-1.	46.	0.
16.625	.792	1332.	1333.	-1.	46.	0.
16.646	.812	1361.	1361.	-0.	45.	0.
16.667	.833	1389.	1389.	0.	45.	0.
16.688	.854	1416.	1416.	-1.	44.	0.
16.708	.875	1441.	1443.	-2.	42.	0.
16.729	.896	1467.	1470.	-3.	39.	0.
16.750	.917	1493.	1496.	-2.	36.	0.
16.771	.937	1519.	1522.	-3.	33.	0.
16.792	.958	1545.	1546.	-2.	31.	0.
16.813	.979	1571.	1573.	-1.	29.	0.
16.833	1.000	1598.	1598.	0.	0.	0.

•OWF•

## STATION A5

(a) INTERPOLATED BREACH HYDROGRAPH  
(b) COMPUTED BREACH HYDROGRAPH



Pear nutrlon is 1957. At time 16.50 hours


	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	1957.	1127.	357.	303.	5154.
CPS	55.	32.	16.	9.	1660.
INCHES		9.53	12.08	12.11	12.11
MM		242.10	306.75	307.61	307.61
AC-FT		559.	709.	710.	710.
THOUS CUM M		689.	874.	876.	876.

THE DAM HYDROGRAPH WAS DEVELOPED USING A TIME INTERVAL OF .021 HOURS DURING BREACH FORMATION.  
 DOWNSTREAM CALCULATIONS WILL USE A TIME INTERVAL OF .167 HOURS.  
 THIS TABLE COMPARES THE HYDROGRAPH FOR DOWNSTREAM CALCULATIONS WITH THE COMPUTED BREACH HYDROGRAPH.

TIME (HOURS)	TIME FROM BEGINNING OF BREACH (HOURS)	COMPUTED		ERROR (CFS)	ACCUMULATED ERROR (CFS)	ACCUMULATED ERROR (PC-Ft.)
		INTERPOLATED HYDROGRAPH (CFS)	BREACH HYDROGRAPH (CFS)			
14.333	0.000	371.	371.	0.	0.	0.
14.354	.021	386.	382.	5.	5.	5.
14.375	.042	401.	393.	6.	12.	12.
14.396	.063	416.	407.	9.	22.	22.
14.417	.083	431.	422.	10.	32.	32.
14.438	.104	446.	437.	9.	40.	40.
14.458	.125	461.	451.	7.	47.	47.
14.479	.146	476.	472.	4.	51.	51.
14.500	.167	491.	491.	0.	51.	51.
14.521	.188	513.	511.	3.	54.	54.
14.542	.208	536.	531.	4.	58.	58.
14.563	.229	558.	553.	5.	63.	63.
14.583	.250	580.	575.	5.	68.	68.
14.604	.271	602.	597.	5.	73.	73.
14.625	.292	625.	621.	4.	77.	77.
14.646	.313	647.	645.	2.	80.	80.
14.667	.333	669.	669.	0.	80.	80.
14.688	.354	695.	694.	1.	81.	81.
14.708	.375	722.	720.	2.	83.	83.
14.729	.396	748.	746.	2.	85.	85.
14.750	.417	774.	772.	2.	87.	87.
14.771	.438	800.	799.	1.	88.	88.
14.792	.458	826.	826.	1.	89.	89.
14.813	.479	853.	852.	0.	89.	89.
14.833	.500	879.	879.	0.	89.	89.
14.854	.521	907.	905.	2.	91.	91.
14.875	.542	936.	932.	3.	94.	94.
14.896	.563	964.	959.	5.	99.	99.
14.917	.583	992.	986.	6.	105.	105.
14.938	.604	1021.	1014.	7.	112.	112.
14.958	.625	1049.	1044.	5.	117.	117.
14.979	.646	1078.	1075.	3.	120.	120.
15.000	.667	1106.	1106.	-0.	120.	120.
15.021	.688	1137.	1137.	-0.	119.	119.
15.042	.708	1168.	1168.	-0.	118.	118.
15.063	.729	1199.	1199.	-1.	117.	117.
15.104	.771	1260.	1261.	-1.	117.	117.
15.125	.792	1291.	1292.	-1.	116.	116.
15.146	.812	1322.	1323.	-0.	116.	116.
15.167	.833	1353.	1353.	0.	116.	116.
15.188	.854	1383.	1383.	-1.	115.	115.
15.208	.875	1412.	1414.	-1.	114.	114.
15.229	.895	1442.	1443.	-1.	113.	113.
15.250	.917	1472.	1473.	-1.	111.	111.
15.271	.937	1501.	1503.	-2.	110.	110.
15.292	.958	1531.	1532.	-1.	109.	109.
15.313	.979	1561.	1561.	-1.	107.	107.
15.333	1.000	1590.	1590.	0.	107.	107.

STATION A5

(+) POINTS AT NORMAL TIME INTERVAL  
 (0) INTERPOLATED BREACH HYDROGRAPH  
 (P) COMPUTED BREACH HYDROGRAPH  
 800. 1000. 1200. 1400. 1600.



DAM BRACH DATA  
 10. 1.00 521.60 1.00 529.90 550.00

STATION A5, PLAN 2, RATIO 1

STATION A5, PLAN 2, RATIO 3

END-OF-PERIOD HYDROGRAPH ORDINATES

	OUTFLC1	3.	3.	4.	4.
1.	1.	2.	3.	4.	5.
4.	5.	5.	5.	5.	5.
6.	6.	6.	6.	6.	6.
6.	6.	6.	6.	6.	6.
6.	6.	6.	6.	6.	6.
6.	6.	6.	6.	6.	6.
20.	23.	26.	28.	31.	34.
48.	50.	53.	55.	57.	59.
68.	70.	72.	77.	86.	99.
202.	239.	265.	295.	326.	371.
584.	618.	738.	980.	1431.	1816.
1797.	1606.	1438.	1257.	1129.	1030.
668.	620.	601.	576.	549.	520.
376.	351.	329.	315.	300.	246.
216.	204.	192.	181.	171.	164.
129.	123.	117.	112.	106.	101.
77.	72.	68.	64.	60.	56.
41.	38.	35.	33.	31.	29.
					STORAGE
115.	115.	115.	115.	115.	115.
116.	116.	116.	116.	116.	116.

116.	116.	116.	116.	116.	116.	116.	116.	116.	116.
116.	116.	116.	116.	116.	116.	116.	116.	116.	116.
116.	116.	116.	116.	116.	116.	116.	116.	116.	116.
117.	118.	118.	118.	118.	118.	119.	119.	119.	119.
121.	121.	121.	121.	122.	122.	122.	122.	123.	123.
123.	123.	124.	124.	125.	125.	127.	129.	131.	133.
139.	141.	144.	147.	149.	152.	154.	157.	159.	161.
165.	164.	166.	168.	172.	177.	181.	183.	182.	180.
177.	175.	172.	171.	169.	169.	169.	169.	167.	166.
165.	165.	164.	162.	161.	159.	158.	156.	155.	154.
152.	151.	150.	148.	147.	146.	144.	143.	142.	141.
140.	139.	138.	137.	136.	135.	134.	135.	132.	131.
131.	130.	129.	128.	128.	127.	127.	126.	125.	125.
124.	124.	123.	123.	122.	122.	121.	121.	120.	120.
126.	126.	126.	126.	119.	118.	118.	118.	116.	116.

				STAGE					
529.9	529.9	529.9	529.9	529.9	529.9	529.9	529.9	529.9	529.9
529.9	529.9	529.9	529.9	529.9	529.9	529.9	529.9	529.9	529.9
529.9	529.9	529.9	529.9	529.9	529.9	529.9	529.9	529.9	529.9
529.9	529.9	529.9	529.9	529.9	529.9	529.9	529.9	529.9	529.9
530.0	530.0	530.1	530.1	530.1	530.1	530.1	530.1	530.0	530.0
530.2	530.2	530.2	530.2	530.2	530.2	530.3	530.3	530.3	530.3
530.3	530.3	530.4	530.4	530.4	530.4	530.5	530.6	530.7	530.9
531.1	531.2	531.3	531.3	531.3	531.4	531.6	531.7	531.8	531.9
532.0	532.1	532.2	532.3	532.3	532.4	532.6	532.8	533.0	533.0
532.6	532.7	532.6	532.5	532.5	532.4	532.4	532.4	532.4	532.4
532.1	532.1	532.1	532.0	532.0	532.0	531.9	531.9	531.8	531.7
531.7	531.7	531.6	531.6	531.5	531.5	531.4	531.4	531.3	531.2
531.2	531.2	531.1	531.1	531.0	531.0	530.9	530.9	530.8	530.8
530.7	530.7	530.6	530.6	530.6	530.6	530.5	530.5	530.4	530.4
530.4	530.4	530.3	530.3	530.3	530.3	530.3	530.2	530.2	530.2
530.2	530.1	530.1	530.1	530.1	530.1	530.1	530.1	530.0	530.0

PEAK OUTFLOW IS 2206, AT TIME 16:33 HOURS

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	2206.	953.	306.	259.	4109.
CPS	62.	27.	9.	7.	1249.
INCHES		8.06	10.34	10.36	10.36
MM		204.72	262.53	263.18	263.18
AC-FT		473.	606.	608.	608.
AC-FT		583.	748.	749.	749.
THOUS CU M					

## HYDROGRAPH ROUTING

ROUTE PREACH OUTFLOW HYDROGRAPH THROUGH STAR LAKE LOWER RESERVOIR

1STAQ	ICOMP	ICON	ITAPP	JPLT	JFPT	INAME	1STAGE	IAUTO
At	1	0	1	0	0	0	0	0

ALL PLANS HAVE SAME

ROUTING DATA									
CLOSS	CLOSS	Avg	IRES	ISAME	INPT	IPMP	STORA	ISPRAT	LSTR
0.0	0.000	0.00	1	1	0	0	50.	-1	0
NSTPS	NSTNL	LAG	AMSKK	X	TSK				
1	0	0	0.000	0.000	0.000				
STAGE	524.10	524.20	525.30	526.40	526.20	527.00			
FLOW	6.00	2.00	163.00	410.00	475.00	2070.00			
CAPACITY	0.	50.	52.	54.	56.	57.	60.		
ELEVATION	509.	524.	524.	525.	526.	526.	527.		
CREL	SPWID	CCOD	EXPV	ELEV	COOL	CAREA	EXPL		
524.1	0.0	0.0	0.0	0.0	0.0	0.0	0.0		
DAH DATA									
TOPEL	CCOD	EXTD	DAPWID						
525.3	0.0	0.0	0.						

STATION AG, PLAN 1, RATIO 3

END-OF-PERIOD HYDROGRAPH ORDINATES

OUTFLOW	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	1.	1.	1.	1.
1.	1.	1.	1.	1.	1.	1.	1.
2.	2.	2.	2.	2.	2.	5.	6.
3.	4.	4.	4.	4.	4.	12.	16.

10.	20.	23.	26.	29.	32.	34.	37.
45.	48.	51.	53.	55.	57.	60.	63.
67.	68.	70.	73.	79.	89.	102.	118.
102.	215.	246.	277.	306.	345.	426.	567.
1329.	1553.	1435.	1251.	1351.	1484.	1709.	1867.
1P81.							
926.	855.	793.	736.	686.	639.	597.	558.
971.	652.	428.	401.	368.	346.	325.	307.
258.	263.	230.	216.	206.	196.	186.	176.
154.	147.	140.	134.	128.	122.	116.	111.
97.	92.	88.	84.	80.	76.	73.	70.
60.	58.	55.	53.	50.	48.	46.	42.

50.	50.	50.	50.	50.	50.	50.	50.
50.	50.	50.	50.	50.	50.	50.	50.
51.	51.	51.	51.	51.	51.	51.	51.
52.	52.	52.	52.	52.	52.	52.	52.
52.	52.	52.	52.	52.	52.	52.	52.
52.	52.	52.	52.	52.	52.	52.	52.
53.	53.	53.	53.	53.	53.	53.	53.
53.	53.	53.	53.	53.	53.	53.	53.
54.	54.	54.	54.	54.	54.	54.	54.
59.	59.	59.	58.	59.	59.	59.	60.
60.	59.	59.	59.	59.	59.	58.	58.
58.	58.	58.	57.	57.	57.	57.	57.
57.	57.	56.	56.	56.	56.	55.	55.
55.	55.	55.	54.	54.	54.	54.	54.
54.	54.	54.	54.	54.	54.	54.	54.
53.	53.	53.	53.	53.	53.	53.	53.
53.	53.	53.	53.	53.	53.	53.	52.

STORAGE	50.	50.	50.	50.	50.	50.	50.
STAGE	524.1	524.1	524.1	524.1	524.1	524.1	524.1
524.1	524.1	524.1	524.1	524.1	524.1	524.1	524.1
524.1	524.1	524.2	524.2	524.2	524.2	524.2	524.2
524.2	524.1	524.2	524.2	524.2	524.2	524.2	524.2
524.2	524.2	524.2	524.2	524.2	524.2	524.2	524.2
524.2	524.2	524.2	524.2	524.2	524.2	524.2	524.2
524.3	524.2	524.2	524.2	524.2	524.2	524.2	524.2
524.3	524.3	524.3	524.3	524.3	524.3	524.3	524.3
524.3	524.3	524.3	524.3	524.3	524.3	524.3	524.3
524.4	524.3	524.4	524.4	524.4	524.4	524.4	524.4
524.5	524.5	524.5	524.5	524.6	524.6	524.6	524.6
524.6	524.6	524.7	524.7	524.7	524.8	524.9	525.0
525.4	525.4	525.5	525.6	525.6	525.8	526.0	526.3
526.6	526.7	526.7	526.6	526.6	526.7	526.8	526.9
526.9	526.9	526.8	526.7	526.7	526.6	526.6	526.5
526.4	526.4	526.4	526.3	526.3	526.3	526.3	526.2
526.2	526.1	526.1	526.0	525.9	525.8	525.8	525.7
525.6	525.5	525.5	525.5	525.4	525.4	525.4	525.3
525.2	525.2	525.1	525.1	525.1	525.0	525.0	524.9
524.8	524.8	524.8	524.8	524.7	524.7	524.7	524.6
524.6	524.6	524.6	524.5	524.5	524.5	524.5	524.5

PEAK OUTFLOW IS 1954. AT TIP! 16.50 HOURS

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS 1954.	1126.	357.	302.	51301.
CMS 55.	32.	10.	9.	1455.
INCHES IN.	9.53	12.07	12.07	12.07
MM MM	241.96	306.50	306.57	306.57
AC-FT	557.	70P.	70P.	70P.
THOUS. CU M	6P9.	873.	873.	873.

**STATION A6, PLAN 2, RATIO 3**  
**END-OF-PERIOD HYDROGRAPH ORDINATES**

OUTFLUX							STORAGE						
0	0	0	0	0	0	0	0	0	0	0	0	0	0
0	0	1	2	6	20	48	68	76	123	163	195	215	235
0	0	1	2	6	20	51	70	74	114	145	163	182	215
1	1	1	2	7	26	53	73	77	117	142	162	182	215
2	2	2	2	8	29	55	79	89	118	144	164	184	218
6	6	6	2	9	32	57	89	102	116	140	160	180	218
18	20	25	20	32	57	89	102	116	135	163	183	205	235
48	48	51	51	53	55	57	60	62	63	65	65	65	65
67	68	70	70	73	79	89	102	116	135	154	154	154	154
82	82	86	86	91	101	106	116	129	145	165	165	165	165
215	215	246	246	277	306	345	361	391	429	465	549	549	549
76	76	94	94	135	176	206	220	227	266	297	2161	2161	2161
123	123	145	145	185	214	244	276	298	328	342	842	842	842
163	163	163	163	180	203	223	244	264	280	294	432	432	432
195	195	205	205	224	242	264	284	309	324	342	237	237	237
215	211	192	171	167	177	166	162	155	148	142	142	142	142
235	129	122	117	111	106	101	96	91	86	81	81	81	81
215	76	72	66	64	60	56	53	50	46	46	46	46	46
195	81	38	35	33	31	29	27	25	23	23	23	23	23
163	91	38	35	33	31	29	27	25	23	23	23	23	23

PEAK OUTFLUX IS AT TIME 3207: 16.33 HOURS

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	2207.	953.	305.	259.	43951.
CPS	63.	27.	9.	7.	1245.
INCHES		8.06	16.32	10.32	10.32
MM	204.65	262.17	262.24	262.24	262.24
AC-FI					
THOUS CU H					

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION STATION AREA PLAN RATIO 1 RATIO 2 RATIO 3 RATIO .25 RATIO .50

HYDROGRAPH AT A1 .86 1 488. 1219. 2438.

( 2.23 ) 2 ( 13.61 ) ( 34.52 ) ( 69.04 )  
 ( 4.88 ) ( 13.81 ) ( 34.52 ) ( 69.04 )

ROUTED TO A2 .86 1 215. 539. 1830.

( 2.23 ) 2 ( 6.09 ) ( 15.26 ) ( 51.02 )  
 ( 2.15 ) ( 6.09 ) ( 15.26 ) ( 51.02 )

HYDROGRAPH AT A3 .24 1 152. 380. 761.

( .62 ) 2 ( 4.31 ) ( 10.77 ) ( 21.55 )  
 ( 152. ) ( 4.31 ) ( 10.77 ) ( 21.55 )

2 COMBINED A4 1.10 1 309. 776. 2297.

( 2.85 ) 2 ( 8.76 ) ( 21.96 ) ( 65.05 )  
 ( 309. ) ( 8.76 ) ( 21.96 ) ( 65.05 )

ROUTED TO A5 1.10 1 226. 1596. 1957.

( 2.85 ) 2 ( 6.45 ) ( 15.24 ) ( 55.43 )  
 ( 226. ) ( 6.45 ) ( 15.21 ) ( 62.48 )

ROUTED TO A6 1.10 1 227. 1570. 1955.

( 2.85 ) 2 ( 6.44 ) ( 15.17 ) ( 55.33 )  
 ( 227. ) ( 6.44 ) ( 15.27 ) ( 62.50 )

## SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1				INITIAL VALUE	SPILLWAY CREST	TOP OF DAP
	ELEVATION	530.60		530.60	534.00	
	STORAGE	210.		210.	300.	
	OUTFLOW	6.		6.	563.	
RATIO	MAXIMUM OF RESERVOIR DEPTH PHF U.S.ELEV	MAXIMUM STORAGE OVER DAM	AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF FAILURE HOURS
.10	531.8A	0.00		244.	215.	0.00
.25	533.85	0.00		296.	539.	0.00
.50	535.22	1.22		343.	1830.	2.83
						16.67
						16.67
						16.33
						0.00

PLAN 2				INITIAL VALUE	SPILLWAY CREST	TOP OF DAP
	ELEVATION	530.60		530.60	534.00	
	STORAGE	210.		210.	300.	
	OUTFLOW	6.		6.	563.	
RATIO	MAXIMUM OF RESERVOIR DEPTH PHF U.S.ELEV	MAXIMUM STORAGE OVER DAM	AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF FAILURE HOURS
.10	531.8A	0.00		244.	215.	0.00
.25	533.85	0.00		296.	539.	0.00
.50	535.22	1.22		343.	1830.	2.83
						16.67
						16.67
						16.33
						0.00

## SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 ..... SPILLWAY CREST ..... INITIAL VALUE ..... TOP OF DAM

ELEVATION	529.90	531.60
STORAGE	115.	150.
OUTFLOW	0.	334.

RATIO OF PF TO N.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW POURS	TIME OF FAILURE HOURS
.10	531.20	0.00	191.	228.	0.00	17.67
.25	531.05	.25	156.	1698.	.63	16.83
.50	531.74	.14	154.	1957.	.77	16.50

PLAN 2 ..... SPILLWAY CREST ..... INITIAL VALUE ..... TOP OF DAM

ELEVATION	529.90	531.60
STORAGE	115.	150.
OUTFLOW	0.	334.

RATIO OF PF TO N.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW POURS	TIME OF FAILURE HOURS
.10	531.20	0.00	191.	228.	0.00	17.67
.25	532.11	.51	165.	643.	4.00	17.00
.50	533.08	.48	183.	2206.	6.17	16.33

## SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....				INITIAL VALUE	SPILLWAY CREST	TOP OF DAM	
RATIO OF RESERVOIR P.M.F. V.S.ELEV	ELEVATION STORAGE OUTFLOW	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	MAX OUTFLOW CFS	TIME OF FAILURE HOURS
.10	525.48	.18	55.	227.	3.50	17.83	0.00
.25	526.75	1.45	59.	1570.	7.83	16.83	0.00
.50	528.94	1.68	60.	1554.	9.03	16.50	0.00

PLAN 2 .....				INITIAL VALUE	SPILLWAY CREST	TOP OF DAM	
RATIO OF RESERVOIR P.M.F. V.S.ELEV	ELEVATION STORAGE OUTFLOW	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	MAX OUTFLOW CFS	TIME OF FAILURE HOURS
.10	525.48	.18	55.	227.	3.50	17.83	0.00
.25	526.29	.99	57.	695.	7.33	17.00	0.00
.50	527.07	1.77	60.	2207.	9.33	16.33	0.00

## APPENDIX 4

### REFERENCES

#### LAKE TELEMARK DAM

1. Chow, Ven Te, Open Channel Hydraulics, McGraw Hill Book Company, New York, 1959.
2. King, H.W. and E.F. Brater, Handbook of Hydraulics, McGraw-Hill Book Company, New York, Fifth Edition 1963.
3. Schway, G.O., R.K. Frevert, T.W. Edmister, and K.K. Barnes, Soil and Water Conservation Engineering, The Ferguson Foundation Agricultural Engineering Series, John Wiley and Sons, Inc., New York, 1966, 683 pp.
4. U.S. Army Corps of Engineers, Hydrologic Engineering Center, Flood Hydrograph Package (HEC-1) for Dam Safety Inspections Users Manual, Davis, California, September 1978.
5. United States Department of Interior, Bureau of Reclamation, Design of Small Dams, U.S. Government Printing Office, Washington, 1977, 816 pp.
6. U.S. Department of Interior, Geological Survey, 7.5-Minute Series (topographic) maps, scale 1:24000, Contour Interval 20 feet: Dover, New Jersey, (1954), Boonton, New Jersey, (1954).
7. U.S. Department of Agriculture, Soil Conservation Service, Urban Hydrology for Small Watersheds, Technical Release No. 55, Washington, 1975.
8. U.S. Department of Commerce, Weather Bureau, "Seasonal Variation of the Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1000 Square Miles and Durations of 6, 12, 24, and 48 Hours", Hydrometeorological Report No. 33, Washington, 1977, 816 pp.